# LAND APPLICATION OF BIOSOLIDS SITE INSPECTION FORM

GENERAL INFORMATION:				DATE: 9/23/2004 telephone; 9/24/2004 onsite			
COUNTY: Spotsylvania CONTRACTOR/MUNICIPALITY: Recyc Systems, Inc.							
NAME (OWNER/OPERATOR): V. Earl Dickinson							
				ERMIT NO: VDHBUR 95			
FIELD NO: SPVED 01				ACRES: @ 13.5 (applied acres @ 3 - 3.5)			
OTHERS PRESENT: Buddy White & Jack Bright, RECYC							
FIELD DATA/OBSERVATIONS:				TIME: 0930			
WEATHER: Partly Cloudy				SOIL CONDITIONS: Moist			
BIOSOLIDS SOURCE: Blue Plains				BIOSOLIDS TYPE: Lime Stabilized			
SOIL pH: 5.1 (date 9/22/2004)				SOLIDS CONTENT OF BIOSOLIDS (%): @ 26			
APPLICATION RATE: 22.0WT target rate							
CROP AND EXPECTED YIELD: Tallgrass hay							
LOAD TO DATE (WT): 71.09 WT total							
BIOSOLIDS APPLIED:	( ) LIQUID ( X ) DEWATERED						
MODE OF APPLICATION:	(X)	(X) SURFACE (X) SURFACE W/INCORP. ( ) INJECTION					
APPLICATION LIMITED	(X)	(X) NITROGEN () pH					
BY:							
	( ) MAX. HYDRAULIC LOADING (LIQUID BIOSOLIDS)						
( ) MAX. SOLIDS LOADING (15 DRY TONS/ACRE)							
( ) OTHER (SPECIFY):							
FIELD OBSERVATIONS						<u>YES</u>	<u>NO</u>
BUFFERS OBSERVED:						X	
UNIFORM APPLICATION:						X	
PROPER FIELD RECORDS:						X	
SIGNS OF RUNOFF:							X
TRUCKS NON-SPILL/WATERTIGHT:							
	CONDITION OF HAUL ROUTE SATISFACTORY:					X	
ODORS PRESENT: (	( ) NC	NE		(X) NORMAL	`	) ABOVE	
				low odor	NC	DRMAL*	
OVERALL CONDITION OF S	$ITF \cdot$	(X)GOOD		( ) FAIR	(	) POOR	

## **COMMENTS:** (\*explain):

## PAN = Plant Available Nitrogen

### 9/23/2004

Writer received a voicemail message from Ms. Susan Trumbo (Recyc Systems), asking that I return her call. Her call was returned at approximately 12:00PM, and she said that an unpermitted field in Spotsylvania County had been spread with Blue Plains lime stabilized biosolids. Ms Trumbo indicated that land application to the field had ceased and the field had not been completed.

#### 9/24/2004

Writer inspected the site and found that land application had occurred on a field located to the south and west of the intersection of SR601 and 726. This field had been included in the original permit application submittal, but had been deleted from the application by VDH due to neighbor concerns. As a result, the field was not permitted, and the permittee failed to revise the site specific information supplied to field personnel.

Setback distances were in compliance with regulations. Odors present at the site were minimal. Application was uniform and had utilized approximately 3.3 acres. Application records indicate a target rate of approximately 140-150lbs PAN supplied by the biosolids.

**COPIES:** VDH – Div. of Wastewater Engineering (permit file)

Spotsylvania County Administrator

Susan Trumbo - Recyc Systems, Inc. (via email)

Chris Peot – DC WASA (via email)